

AMENDMENTS TO THE SPECIFICATION

Amend the specification in accordance with the instructions that follow:

[0027] The inventors of the present application have found the PA6T/6I molding materials highly filled with glass fibres with long flow length ~~a-peer~~ show unsatisfactory surface quality. Especially for black or dark-coloured molding materials they show optically visible defects such as whitish or grey markings (that is impairment of the colour depth effect) and/or wrinkle formations and/or so-called "tiger skin structures", i. e. scale-like, non-smooth surface structure. Additionally, the defects can strongly impair the varnishability of the parts and/or require additional expenditure for varnishings which can be especially disadvantageous for molded parts in motor vehicles.